

MAKE-UP REMOVER

INGREDIENTS	%W/W
Part A:	
EMULGADE F (Cetearyl Alcohol (and) PEG-40 Castor Oil (and) Sodium Cetearyl Sulfate)	8.0
CUTINA CP (Cetyl Palmitate)	4.0
CUTINA BW (Glyceryl Hydroxystearate (and) Cetyl Palmitate (and) Microcrystalline Wax (and) Trihydroxystearin)	2.5
CETIOL J 600 (Oleyl Erucate)	3.0
CETIOL LC (Coco Caprylate/Caprates)	3.5
Part B:	
Water	78.9
Dowicil 200 (Quaternium 15)	0.1
Part C:	
Fragrance	q.s.

## Procedure:

Mix and heat Part A - 65-70C. Heat Part B - 65-70C and add to A. Cool to 45C while mixing and add fragrance. Package at 35C.

## Comments:

Non-greasy oil-free makeup remover. Ideal for oily skin.

SOURCE: Henkel Corp.: Personal Care Products Formulary:  
Formula HOB-203-2

MAKE-UP REMOVER OIL

RAW MATERIALS	% By Weight
MAZER MAZOL 1400	12.0
MAZER MAPEG 200 DL	6.0
Mineral Oil (70 SUS)	82.0
Perfume	q.s.

## Procedure:

Mix at room temperature. Filter. Pack. Low viscosity oil for removing make-up can be rinsed or tissue off.

SOURCE: Mazer Chemicals, Inc.: Cosmetic Formularies T-20D:  
Formulation